


FIG. I



F I G. 2




FIG. 3




FIG. 4

TIME (min)	SET TEMPERATURE (°C)	CHANGE RATE OF SET TEMPERATURE (°C/min)
	(Set Point)	(Ramp Rate)
t 0~t1	300	0
t 1~t 2	300~310	1 0
t 2~t 3	310~350	2 0
t 3~t 4	350~400	5 0
t 4~t 5	400~500	100
t5~t6	500	0
t6~t7	500~400	-100
t7~t8	400~350	- 5 0
t8~t9	350~300	-10
t 9~	300	0

F I G. 5




FIG. 6